

## Rejected Colonies

S.No	App.NO	Name	Father Name	Colony Name	Village	Address
1	194271	Jasvir Singh	Charanjit Singh	Didar Nagar	khairabad	Vill Khairabad, Rupnagar
2	306006	HBIL FARMS PVT LTD		PADARPUR	PADARPUR	Opp Cold Storage , Mukatsar
3	108627	Mann Singh	Gurbux Singh	Preet Colony	Marauli Kalan	H.No-545,W.No-1,Surjit Nagar Morinda
4	188250	Sewa Singh	Jit Singh	Khairabad Colony	khairabad	#5432, Ram Nagar ,Rupnagar
5	104868	sarbjit Singh	Nand Lal	Hari Enclave	Haveli Kalan	#716/1-41A, Chandigarh
6	191892	Baljeet Singh	Tehal Singh	inder Enclave, Haveli Kalan	Haveli Kalan	Vill hinder Nagar, Roopnagar
7	141394	Terrain Estate & Villas Pvt Ltd		Terrain City	Thappal	SCO 9,2nd floor Leela Bhawan,Patiala

<b>Remarks</b>
No development work at site as per report of DTP Colony is to be rejected as per recomedation of STP
As per STP SAS Nagar report area of colony fall in PLPA area Colony is to be rejected.
As per STP report High tension Electricity line passes on the plots and the road with is not sufficent , colony is to be rejected
Road width is 15' No fire tender movement . colony is to be rejected
No development work at site as per report of DTP Colony is to be rejected as per recomedation of STP
No development work at site as per report of DTP Colony is to be rejected as per recomedation of STP
As per STP SAS Nagar report area of colony fall in PLPA area Colony is to be rejected.